

501 Waterford, C Wing, C.D.Barfiwala Marg(Juhu Lane), Andheri(W), Mumbai 400 058. INDIA

Phone +91 22 42184218 Fax +91 22 42184350

Email tcmktg@sarex.com URLwww.sarex.com

PRODUCT LITERATURE

FERAFIX-PDM

Product Information

Ferafix-PDM is newly developed formaldehyde free, powder dye fixing agent for cellulosic's dyed with reactive dyes and direct dyes and Indigo dyed and Sulphur dyed denims. Ferafix-PDM shows excellent improvement in washing fastness, perspiration fastness and water fastness. It does not impair the shade of the fabric and no adverse effect on the light fastness property of dyed fabric. It is applicable by exhaust as well as pad application.

Key Features & Benefits

Key features Benefits

Formaldehyde-free Suitable for babywear

No adverse effect on light Suitable for all shades

Fastness

Powder form Easy to handle

General Characteristics

Physical appearance : White powder : Cationic Ionic nature pH of 1% solution : 6 + /-1

Miscibility : Soluble in water

Compatibility : Compatible with cationic and nonionic products : Stable to dilute acids and dilute alkalies Stability

Application

For Reactive dyed fabrics

After thorough soaping of reactive dyed fabrics, treat in a fresh bath with below recipe:

Exhaust Process Continuous Process _____ -----

Dosage Dosage : 5-7 gpl : 0.5-0.7% Dosage : 0.5-0.7% Bath pH : 5.0-5.5 Pick-up : 65-70% Bath pH Drying Bath Temp : 30-40 deg.C : 5.0-5.5

: 15-30 min.: 130-170 deg.C



501 Waterford, C Wing, C.D.Barfiwala Marg(Juhu Lane), Andheri(W), Mumbai 400 058. INDIA

Phone +91 22 42184218 Fax +91 22 42184350

Email tcmktg@sarex.com URLwww.sarex.com

PRODUCT LITERATURE

FERAFIX-PDM

For Indigo & Sulphur dyed fabrics

Exhaust Process Padding Process

Dosage : 0.7-1.7% Dosage :7-17 gpl
Bath pH : 5.0-5.5 Pick-up :65-70%
Bath Temp : 30-40 deg.C Bath pH :5.0-5.5
Time. : 15-20 min. Drying :110-130 deg.C

For Direct dyed fabrics

After thorough soaping of Direct dyed fabrics, treat in a fresh bath with below recipe:

Exhaust Process Padding Process

Dosage : 1.5-2.5% Bath pH : 3.5-4.5 Dosage : 15-25 gpl : 65-70% Pick-up Bath Temp : 30-40 deg.C Bath pH : 3.5-4.5 Time. : 15-30 min. Drying : 130-170 deg.C

Instructions for Dilution

Procedure to prepare 20% Ferafix-PDM

- Take 80 parts of DM water
- To this, gradually add 20 parts Ferafix-PDM with constant stirring
- Continue stirring to obtain homogenous solution
- Filter it to remove un-dissolved particles if any.

Precautions

: Store in cool, ventilated shed away from Storage

> heat and direct sunlight. Storage temperature should not exceed 35 deg C. Close lids firmly to avoid contact with air and moisture.

Shelf Life : 9 months from the date of manufacturing, if

stored under controlled conditions.

[The above information is given in good faith and is without warranty] $[\ \mathsf{Prod}.\mathsf{Code} : \mathsf{L010923}.\mathsf{docx} \ | \quad \mathsf{Last} \ \mathsf{Upd}. \ \mathsf{On} : \mathsf{07/08/24} \] \ [\mathsf{PVR}]$

This is a computer generated report. Hence not signed.